

	PC	POC	PCF	PL	PLH	PB	PD	PX	PLL	PLF	PMF	PH	PHF	JSC
5/32-U	500	500	200	200	200	100	100	100	100	100	200	200	200	200
5/32-N1	300	300	200	150	150	100	100	100	100	100	200	100	100	100
5/32-N2	300	300	100	100	100	100	100	100	100	100	100	100	100	100
1/4-U	300	300	200	150	150	100	100	100	100	100	200	150	150	150
1/4-N1	300	300	200	100	100	100	100	100	100	100	100	100	100	100
1/4-N2	200	200	100	100	100	100	100	100	100	100	100	100	100	100
1/4-N3	150	150	100	100	100	100	100	100	100	100	100	100	100	100
1/4-N4	100	100	100	100	100	100	100	100	100	100	100	100	100	100
5/16-N1	200	200	200	100	100	100	100	100	100	100	100	100	100	100
5/16-N2	200	200	100	100	100	100	100	100	100	100	100	100	100	100
5/16-N3	150	150	100	100	100	100	100	100	100	100	100	100	100	100
5/16-N4	100	100	100	100	100	100	100	100	100	100	100	100	100	100
3/8-N1	100	100	100	100	100	100	100	100	100	100	100	100	100	100
3/8-N2	100	100	100	100	100	100	100	100	100	100	100	100	100	100
3/8-N3	100	100	100	100	100	100	100	100	100	100	100	100	100	100
3/8-N4	100	100	100	100	100	100	100	100	100	100	100	100	100	100
1/2-N2	100	100	100	100	100	100	100	100	100	100	100	100	100	100
1/2-N3	100	100	100	100	100	100	100	100	100	100	100	100	100	100
1/2-N4	100	100	100	100	100	100	100	100	100	100	100	100	100	100

	PU	PZA	PE PY	PV	PM	PP	PK	PIJ	PLJ	PYJ	JSU
5/32	200	100	100	200	200	1000	100	1000	100	100	100
1/4	150	100	100	150	100	500	100	500	100	100	100
5/16	100	100	100	100	100	250	100	250	100	100	100
3/8	100	100	100	100	100	200	100	200	100	100	100
1/2	100	100	100	100	100	100	---	100	100	100	100

	PG	PW	PEG	PKG	PIG	PGJ	PLGJ	PWJ	PKJ
1/4-5/32	150	100	100	100	500	200	100	100	100
5/16-5/32	---	---	---	100	---	150	---	---	100
5/16-1/4	100	100	100	100	250	100	100	100	100
3/8-1/4	---	---	---	100	---	100	---	---	100
3/8-5/16	100	100	100	100	200	100	100	100	100
1/2-1/4	---	---	---	---	---	100	---	---	---
1/2-5/16	---	---	---	---	---	100	---	---	---
1/2-3/8	100	100	100	---	100	100	100	100	---

	PKD		PKD
1/4-5/32-N1	100	08-06-02	100
5/16-1/4-N2	100	10-08-03	100